



## Procedure

### Preparation

1. The technician will be instructed to reduce the potential of an airborne infection.

3. When practical, install a HEPA vacuum to minimize the potential of airborne particulates.

4. The technician will wear appropriate personal protective equipment (PPE) in the infection area.

5. After the procedure, the technician will clean the area to nursing administration and accounting.